



# Return to Vendor Advice Report

RTV ID : 23021

Report Date: 5-Feb-25  
Page: 1 of 6

|                |                        |                 |                                          |
|----------------|------------------------|-----------------|------------------------------------------|
| VENDOR NBR :   | 43                     | VENDOR ADDRESS: | AL FUTTAIM WATCHES AND JEWELLERY CO.LLC. |
| CONTAINER ID:  | 0000000000000000376547 |                 | 7916, DUBAI,<br>Not Applicable, AE       |
| AUTHORIZATION: | RA# RTV/001            |                 |                                          |

| Item Id   | UPC           | Description                                      | Container Qty | Total Units | Container Weight |
|-----------|---------------|--------------------------------------------------|---------------|-------------|------------------|
| 110328757 | 1100005450073 | RAYMOND WEIL MQ SS 42MM WDL 5588ST00300          | 1.00          | 1.00        | 0.00             |
| 110558450 |               | WESTAR MQ ACT BRC G RND CHR QX1 90103            | 1.00          | 3.00        | 0.00             |
| 110579891 | 7611784041344 | RAYMOND WEIL LQ TANG BRC SSD 30MM 5960STS00995   | 1.00          | 1.00        | 0.00             |
| 110666515 | 7611784041351 | RAYMOND WEIL LQ TANG BRC TTRGD 30MM 5960SP500995 | 1.00          | 1.00        | 0.00             |
| 110773116 | 7611784042839 | RAYMOND WEIL MA FREL BRC SSBLU 43MM 2760ST465001 | 1.00          | 1.00        | 0.00             |
| 110905127 | 7611784043560 | RAYMOND WEIL MQ TANG SS 42 MM 8260ST320001       | 1.00          | 1.00        | 0.00             |
| 111064824 | 7611784043348 | RAYMOND WEIL MA FREL LST SS 43MM 2731STCBOW01    | 1.00          | 1.00        | 0.00             |
| 111090447 |               | SEIKO MQ 18V1 ASTR BLUDL RUB 8X53 SSE167J1       | 1.00          | 1.00        | 0.00             |
| 111145886 | 7611784045144 | RAYMOND WEIL LQ PARS BRC SS 30MM 5180ST00300     | 1.00          | 1.00        | 0.00             |
| 111145899 | 7611784044857 | RAYMOND WEIL MQ PARS BRC SSYG 41MM 5580STP00308  | 1.00          | 1.00        | 0.00             |
| 111145903 | 7611784044314 | RAYMOND WEIL MQ TANG BRC SS 43MM 8570SP365501    | 1.00          | 1.00        | 0.00             |
| 111246516 |               | SEIKO MA 18V1 PROS BRC ST 3HD DIV LTD. SPB083J1  | 1.00          | 2.00        | 0.00             |
| 111247179 |               | WESTAR LQ PRO BRC L RND 3HD SX1 40202            | 1.00          | 1.00        | 0.00             |
| 111359943 |               | RAYMOND WEIL MQ TANG BRC SS 42MM 8280ST1BMY18    | 1.00          | 2.00        | 0.00             |
| 111383766 | 7611784038979 | RAYMOND WEIL MA MAES BRC SS 40MM 2237ST65001     | 1.00          | 1.00        | 0.00             |
| 111383771 | 7611784044437 | RAYMOND WEIL LQ NOEM BRC SS 32MM 5132ST20081     | 1.00          | 1.00        | 0.00             |
| 111383776 |               | RAYMOND WEIL LQ FREL BRC SS 34MM 5634ST80021     | 1.00          | 1.00        | 0.00             |
| 111412024 |               | SEIKO MQ 19V1 PREM BRC ST KIN PERP SNP161P1      | 1.00          | 1.00        | 0.00             |
| 111424098 | 4894138685033 | ALBA LQ 19V1 FAS BRC ST 3HD AH7T19X1             | 1.00          | 1.00        | 0.00             |



## Return to Vendor Advice Report

RTV ID : 23021

Report Date: 5-Feb-25  
Page: 2 of 6

|           |               |                                                  |      |      |      |
|-----------|---------------|--------------------------------------------------|------|------|------|
| 111443446 | 4954628230300 | SEIKO LQ 19V1 CAP DIA BRC ST 3HD SKK881P1        | 1.00 | 2.00 | 0.00 |
| 111443450 |               | SEIKO MA 19V1 PRES LST ST 3HD P.RES SPB093J1     | 1.00 | 1.00 | 0.00 |
| 111450199 | 7611784046301 | RAYMOND WEIL MA FREL BRT 42 MM 2738STP20001      | 1.00 | 1.00 | 0.00 |
| 111450200 | 7611784046271 | RAYMOND WEIL MA FREL BRT SS 42 2738ST50001       | 1.00 | 1.00 | 0.00 |
| 111450262 | 4894138684210 | ALBA LQ 19V1 PRE-PAIR BRC ST 3HD AH7S47X1        | 1.00 | 1.00 | 0.00 |
| 111488266 |               | RAYMOND WEIL MA MAES BRC SS 40MM 2238ST00659     | 1.00 | 1.00 | 0.00 |
| 111593267 |               | GRAND SEIKO MQ 16V1 GS BRC ST 3HD SBGV207G       | 1.00 | 1.00 | 0.00 |
| 111628231 | 7611784047551 | RAYMOND WEIL LQ JASM BRT SS 35 MM 5245ST00661    | 1.00 | 1.00 | 0.00 |
| 111628232 | 7611784047483 | RAYMOND WEIL LQ JASM BRT SSRG 30 MM 5240SP500665 | 1.00 | 1.00 | 0.00 |
| 111628233 | 7611784047520 | RAYMOND WEIL LQ JASM BRT SS 30 MM 5240ST00681    | 1.00 | 3.00 | 0.00 |
| 111628234 |               | RAYMOND WEIL LQ JASM BRT SSYG 30 MM 5240STP00665 | 1.00 | 1.00 | 0.00 |
| 111628235 | 7611784047605 | RAYMOND WEIL LQ JASM BRT SSRG 35 MM 5245SP500661 | 1.00 | 1.00 | 0.00 |
| 112249697 |               | WESTAR LQ ZIN BRC RND 3H TX1 00104STN614         | 1.00 | 2.00 | 0.00 |
| 112249707 |               | WESTAR LQ ZIN BRC RND 2H TX1 00108GPN102         | 1.00 | 3.00 | 0.00 |
| 112249711 |               | WESTAR LQ ZIN BRC RND 2H TX1 00124SPN607         | 1.00 | 1.00 | 0.00 |
| 112249714 |               | WESTAR LQ ZIN BRC RND 3H TX1 00127CBN111         | 1.00 | 5.00 | 0.00 |
| 112249715 |               | WESTAR LQ ZIN BRC RND 3H TX1 00127PPN613         | 1.00 | 6.00 | 0.00 |
| 112249716 |               | WESTAR LQ ZIN MSH RND 3H TX1 00128GPN112         | 1.00 | 4.00 | 0.00 |
| 112249717 |               | WESTAR LQ ZIN MSH RND 3H TX1 00128GPN113         | 1.00 | 3.00 | 0.00 |
| 112298403 |               | WESTAR LQ ZIN BRC RND 2H TX1 00135PPN613         | 1.00 | 1.00 | 0.00 |
| 112298404 |               | WESTAR LQ ZIN BRC RND 2H TX1 00135SPN611         | 1.00 | 2.00 | 0.00 |
| 112298405 |               | WESTAR MQ ACT LST RND Chrono TX1 90253STN103     | 1.00 | 1.00 | 0.00 |
| 112298408 |               | WESTAR MQ ACT BRC RND 3HD TX1 90250BBN903        | 1.00 | 1.00 | 0.00 |
| 112298414 |               | WESTAR LQ ZIN MSH RND 3H TX1 00128PPN613         | 1.00 | 3.00 | 0.00 |



## Return to Vendor Advice Report

RTV ID : 23021

Report Date: 5-Feb-25  
Page: 3 of 6

|           |  |                                                 |      |       |      |
|-----------|--|-------------------------------------------------|------|-------|------|
| 112298417 |  | WESTAR LQ PRO BRC RND 3HDD TX1 40212STN407      | 1.00 | 6.00  | 0.00 |
| 112298418 |  | WESTAR MQ PRO BRC RND 3HD TX1 50213SPN607       | 1.00 | 1.00  | 0.00 |
| 112298419 |  | WESTAR LQ PRO BRC RND 3HD TX1 40213SPN607       | 1.00 | 3.00  | 0.00 |
| 113502530 |  | WESTAR LQ MOPDL 33MM SSBRCCT 00104STN111        | 1.00 | 4.00  | 0.00 |
| 113502531 |  | WESTAR LQ BWNDL 31MM SSBRCCT 00109PPN620        | 1.00 | 5.00  | 0.00 |
| 113502536 |  | WESTAR LQ RGD L 28MM SSBRCCT 00112SPN609        | 1.00 | 2.00  | 0.00 |
| 113502552 |  | WESTAR LQ BLKDL 32MM SSBRCCT 40212STN103        | 1.00 | 3.00  | 0.00 |
| 113502553 |  | WESTAR LQ SILD L 32MM SSBRCCT 40212STN107       | 1.00 | 2.00  | 0.00 |
| 113502554 |  | WESTAR MQ BLKDL 41MM SSBRCCT 50213STN103        | 1.00 | 1.00  | 0.00 |
| 113502555 |  | WESTAR LQ BLKDL 31MM SSBRCCT 40213STN103        | 1.00 | 1.00  | 0.00 |
| 113502557 |  | WESTAR LQ BLUDL 31MM SSBRCCT 40213STN104        | 1.00 | 2.00  | 0.00 |
| 113502559 |  | WESTAR LQ SILD L 31MM SSBRCCT 40213STN107       | 1.00 | 4.00  | 0.00 |
| 113502563 |  | WESTAR LQ CPNGDL 32MM SSBRCCT 40220STN102       | 1.00 | 4.00  | 0.00 |
| 113888928 |  | WESTAR LQ SILD L 31MM TTYGSSBRCCT 00105CBN107   | 1.00 | 2.00  | 0.00 |
| 113888930 |  | WESTAR LQ SILD L 28MM SSBRCCT 00112STN107       | 1.00 | 1.00  | 0.00 |
| 113888931 |  | WESTAR LQ SILD L 36MM TTYGSSBRCCT 00124CBN107   | 1.00 | 4.00  | 0.00 |
| 113888932 |  | WESTAR LQ SILD L 36MM GLDSSBRCCT 00124GPN107    | 1.00 | 3.00  | 0.00 |
| 114032703 |  | WESTAR LQ WHTDL 33MM TTYGSSBRCCT 00108CBN101    | 1.00 | 16.00 | 0.00 |
| 114032704 |  | WESTAR LQ SILD L 33MM RGSSBRCCT 00108PPN607     | 1.00 | 8.00  | 0.00 |
| 114032705 |  | WESTAR LQ SILD L 33MM TTRGSSBRCCT 00108SPN607   | 1.00 | 13.00 | 0.00 |
| 114032706 |  | WESTAR LQ SILD L 33MM SSBRCCT 00108STN107       | 1.00 | 13.00 | 0.00 |
| 114032707 |  | WESTAR LQ CMPDL 30.5MM GLDSSBRCCT 00109GPN112   | 1.00 | 2.00  | 0.00 |
| 114032708 |  | WESTAR LQ WHTMOPDL 30.5MM RGSSBRCCT 00109PPN611 | 1.00 | 7.00  | 0.00 |
| 114032719 |  | WESTAR LQ SILD L 32MM TTRGSSBRCCT 40215SPN607   | 1.00 | 10.00 | 0.00 |



## Return to Vendor Advice Report

RTV ID : 23021

Report Date: 5-Feb-25  
Page: 4 of 6

|           |  |                                            |      |       |      |
|-----------|--|--------------------------------------------|------|-------|------|
| 114032720 |  | WESTAR MQ BLKDL 44MM BRWNSTRP 50228STN883  | 1.00 | 2.00  | 0.00 |
| 114032721 |  | WESTAR MQ WHTDL 40MM GLDSSBRCT 50243GPN101 | 1.00 | 2.00  | 0.00 |
| 114032722 |  | WESTAR MQ WHTDL 42MM BLKSTRP 50244GPN101   | 1.00 | 2.00  | 0.00 |
| 114032724 |  | WESTAR MQ WHTDL 42MM SSBRCCT 50245STN101   | 1.00 | 7.00  | 0.00 |
| 114032725 |  | WESTAR LQ WHTDL 32MM SSBRCCT 40245STN101   | 1.00 | 13.00 | 0.00 |
| 114032726 |  | WESTAR MQ BLKDL 45MM SSBRCCT 90244STN103   | 1.00 | 12.00 | 0.00 |
| 114112989 |  | WESTAR LQ WMOPDL 39MM GLDBRCCT 00127GPN111 | 1.00 | 7.00  | 0.00 |
| 114112999 |  | WESTAR LQ WHTDL 38MM SSBRCCT 00130CBN101   | 1.00 | 8.00  | 0.00 |
| 114113001 |  | WESTAR LQ BLUDL 32.2MM SSBRCCT 40215STN104 | 1.00 | 12.00 | 0.00 |
| 114201411 |  | WESTAR LQ MOPDL SS 00136STN111             | 1.00 | 4.00  | 0.00 |
| 114201412 |  | WESTAR LQ MOPDL SS 00136STN113             | 1.00 | 3.00  | 0.00 |
| 114201414 |  | WESTAR LQ SILD L SS 00137CBN107            | 1.00 | 4.00  | 0.00 |
| 114201419 |  | WESTAR LQ SILD L SS 00137SPN607            | 1.00 | 4.00  | 0.00 |
| 114201434 |  | WESTAR LQ SILD L SS 00139CBN107            | 1.00 | 3.00  | 0.00 |
| 114201435 |  | WESTAR LQ YLWDL SS 00139GPN102             | 1.00 | 3.00  | 0.00 |
| 114218270 |  | WESTAR LQ ZIN SILD L YGSS 00139SPN607      | 1.00 | 6.00  | 0.00 |
| 114218271 |  | WESTAR LQ ZIN PNKDL RGSS 00139SPN609       | 1.00 | 4.00  | 0.00 |
| 114218275 |  | WESTAR LQ ZIN SILD L SS 00139STN607        | 1.00 | 5.00  | 0.00 |
| 114218282 |  | WESTAR LQ ZIN BLUD L SS 00140STN104        | 1.00 | 5.00  | 0.00 |
| 114218283 |  | WESTAR LQ ZIN SILD L SS 00140STN107        | 1.00 | 4.00  | 0.00 |
| 114218290 |  | WESTAR LQ ZIN MOPDL BLKLTHR 00144PPN611    | 1.00 | 6.00  | 0.00 |
| 114218292 |  | WESTAR LQ ZIN PNKMOPDL BLKLTHR 00144PPN619 | 1.00 | 5.00  | 0.00 |
| 114269254 |  | WESTAR LQ ZIN BLKMOP 37MM 00161GPN113      | 1.00 | 3.00  | 0.00 |
| 114269256 |  | WESTAR LQ ZIN BLKMOP 37MM 00161PPN613      | 1.00 | 3.00  | 0.00 |



## Return to Vendor Advice Report

RTV ID : 23021

Report Date: 5-Feb-25  
Page: 5 of 6

|           |  |                                         |      |      |      |
|-----------|--|-----------------------------------------|------|------|------|
| 114269260 |  | WESTAR LQ ZIN SIDL 35MM 00162GPN107     | 1.00 | 3.00 | 0.00 |
| 114269261 |  | WESTAR LQ ZIN SIDL 35MM 00162STN107     | 1.00 | 3.00 | 0.00 |
| 114269272 |  | WESTAR LQ ZIN BLKMOP 32MM 00165SPN613   | 1.00 | 3.00 | 0.00 |
| 114297133 |  | WESTAR LQ ZIN PNKMOP 30MM 00148SPN619   | 1.00 | 5.00 | 0.00 |
| 114297137 |  | WESTAR LQ ZIN SIDL 35MM 00149STN107     | 1.00 | 5.00 | 0.00 |
| 114297141 |  | WESTAR LQ ZIN WHTDL 33MM 00153STN301    | 1.00 | 4.00 | 0.00 |
| 114297142 |  | WESTAR LQ ZIN WHTMOP 33MM 00154STN111   | 1.00 | 6.00 | 0.00 |
| 114297154 |  | WESTAR LQ ZIN WHTMOP 36.5MM 00161STN111 | 1.00 | 5.00 | 0.00 |
| 114297156 |  | WESTAR LQ ZIN CHAMD 35MM 00162GPN102    | 1.00 | 4.00 | 0.00 |
| 114297159 |  | WESTAR LQ ZIN SIDL 35MM 00163PPN607     | 1.00 | 6.00 | 0.00 |
| 114297160 |  | WESTAR LQ ZIN SIDL 35MM 00163STN107     | 1.00 | 6.00 | 0.00 |
| 114297161 |  | WESTAR LQ ZIN WHTMOP 34MM 00164SPN611   | 1.00 | 6.00 | 0.00 |
| 114297162 |  | WESTAR LQ ZIN BLKMOP 34MM 00164SPN613   | 1.00 | 5.00 | 0.00 |
| 114297170 |  | WESTAR LQ ZIN BLUDL 36.5MM 00166SPN104  | 1.00 | 5.00 | 0.00 |
| 114297172 |  | WESTAR LQ ZIN SIDL 34MM 00167CBN107     | 1.00 | 6.00 | 0.00 |
| 114297176 |  | WESTAR LQ ZIN BRNDL 34MM 00167SPN610    | 1.00 | 6.00 | 0.00 |
| 114321243 |  | WESTAR LQ GRNMOP 37MM 00161SPN615       | 1.00 | 4.00 | 0.00 |
| 114321244 |  | WESTAR LQ BLKDL 35MM 00162CBN103        | 1.00 | 4.00 | 0.00 |
| 114321245 |  | WESTAR LQ SIDL 35MM 00162CBN107         | 1.00 | 4.00 | 0.00 |
| 114321248 |  | WESTAR LQ SIDL 35MM 00163CBN107         | 1.00 | 4.00 | 0.00 |
| 114321250 |  | WESTAR LQ CHAMD 35MM 00163GPN102        | 1.00 | 4.00 | 0.00 |
| 114321252 |  | WESTAR LQ BLKMOP 32MM 00165CBN113       | 1.00 | 4.00 | 0.00 |
| 114321258 |  | WESTAR LQ BLKDL 34MM 00167STN103        | 1.00 | 4.00 | 0.00 |
| 114321268 |  | WESTAR LQ SIDL 33MM 00143CBN107         | 1.00 | 4.00 | 0.00 |



# Return to Vendor Advice Report

RTV ID : 23021

Report Date: 5-Feb-25  
Page: 6 of 6

|           |  |                                    |      |      |      |
|-----------|--|------------------------------------|------|------|------|
| 114321269 |  | WESTAR LQ WHTDL 33MM 00143GPN101   | 1.00 | 4.00 | 0.00 |
| 114321271 |  | WESTAR LQ BLKMOP 30MM 00148CBN113  | 1.00 | 3.00 | 0.00 |
| 114321278 |  | WESTAR LQ BLKDL 33MM 00143STN103   | 1.00 | 4.00 | 0.00 |
| 114321279 |  | WESTAR LQ SILD L 33MM 00143STN107  | 1.00 | 4.00 | 0.00 |
| 114321280 |  | WESTAR LQ WHTMOP 30MM 00147STN111  | 1.00 | 4.00 | 0.00 |
| 114321285 |  | WESTAR LQ CHAMMOP 33MM 00160STN112 | 1.00 | 4.00 | 0.00 |
| Total     |  |                                    | 121  | 447  | 0    |

| DC Reverse Logistics |               | Supplier<br>Collected By |
|----------------------|---------------|--------------------------|
| Confirm Return By    | Authorized By |                          |
| Name                 |               |                          |
| Staff No             |               |                          |
| Date                 |               |                          |
| Mobile No            |               |                          |